CREW:	77 WORK ORDER TYPE: MODII	FICATIONS			01-19846-16 ISSUE	DATE 01/06/11	Page 1 Of 1	
Origi:	nator : TRAVIS SMITH er : JOSEPH TANNER	Schedule Date Priority	: : 3A		Date Co	ompleted:	Failure Code:	
Drawi	ng No : No/Cat: 5COXST 0	Clearance	: NO		Complet	ed By :	Signature :	
Project ID : Text ID Shutdown : N No Shutdown Frequency					ccepted By :	Signature :		
Ref No		Last Reading	: No		ading	on	** Delay Codes Legend ** W=Whse C=CrSp T=Tag TL=Tool P=P16 ** Record Time Daily ** De: Emp No Date Hours Code/	lays
1	ASSIST MAINTENANCE WITH INS				USE APPROPRIATE CAUTION DURING			
-	MEGAWATT TRANSDUCERS IN THE BI-POLE CONTROLS. ************************************		. -		INSTALLATION OF THE TRANSDUCERS.			
					CHECK THE CT CIRCUITS BEFORE STARTING THE INSTALLATION PROCESS.	ARTING THE		
	1. ASSIST MAINTENANCE WITTHE NEW MEGAWATT TRANSDUCE				1.00.00.			
	BI-POLE CONTROLS. 2. COMPLETE THE SETUP OF							
	CONTROLS TO OPERATE CORRECT TRANSDUCERS.							
	3. NOTE ON THIS WORK ORDER FOUND AND CORRECTIVE ACTION							

							** IMPORTANT NOTICE ** YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND RESOURE THAT THE REQUIRED PPE IS WORN FOR EVEL JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR	RY S

Job Feedback/Historical Notes:



IP7_005523